Appendix i – Property Compliance KPI Report

Period of reporting: as at 31st July 2024

| Workstream | | Total No. properties in programme | No. compliant properties | No. Non compliant properties | Compliance % | Direction of travel |
|------------|---|---|-----------------------------|------------------------------|--------------|------------------------|
| Gas safety | Domestic LGSR | 4263 | 4262 | 1 | 99.98 | l |
| | Commercial LGSR | 6 | 6 | 0 | 100 | \overleftrightarrow |
| | TSM: Percentage of Gas Safety Checks Compliant (properties) | 4417 | 4416 | 0 | 99.98 | ↓ |
| | Properties requiring gas safety check in next 3 months | 773 | | | | |
| | | No. capped | No. capped over 3 months | | | |
| | Properties with capped gas | 140 | 42 tenanted homes | | | |
| | | No. of overdue LGSR | | | L | |
| | Overdue LGSR <1 month | 1 | | | | |
| | Overdue LGSR 1-3 months | 0 | | | | |
| | Overdue LGSR >3 months | 0 | | | | |

| Comments | As at 31st July there was one property overdue for a gas safety check, this was due to the tenant not providing access. This has been passed to Legal to commence Court action. |
|----------|---|
| | The capped gas properties includes for void properties (80). Where a tenanted property is capped this is referred to the TMO to manage and visit on a quarterly basis due to concerns over tenancy welfare and vulnerabilities. All capped properties remain on the service programme and are checked annually. |

| Workstream | | Total No. properties in programme | No. compliant properties | No. Non compliant properties | Compliance % | Direction of travel |
|-------------------|--|---|--|--------------------------------------|--------------|------------------------|
| Electrical checks | 5 year EICR domestic testing cycle | 4619 | 4270 | 349 | 92.44 | |
| | 10 year EICR domestic testing cycle | 4619 | 4617 | 2 | 99.96 | |
| | Communal EICRs | 340 | 340 | 0 | 100.00 | |
| | | Overdue high risk C1 (danger to life | Overdue medium risk actions C2 (potentially dangerous) | Overdue high risk C1 (danger to life | | |
| | Overdue electrical remedials <3 months | Unknown | Unknown | Unknown | | |
| | Overdue electrical remedials 3-6 months | Unknown | Unknown | Unknown | | |
| | Overdue electrical remedials 6-12 months | Unknown | Unknown | Unknown | | |
| | Overdue electrical remedials >12 months | Unknown | Unknown | Unknown | | |
| | Electrical safety inspections due in next 3 months | 6 | | | | |

| Comments | One property has been ser Of remaining two, notices to The 10 year programme is b programme are due to access Currently unable to report or completion is to be reviewed Progress has slowed, due to | at 7-day letter; we await o quit are expected soc eing replaced by a 5 ye is issues and being put a status of actions arisin to enable future report access and reduced re ar certification by Aug 2 and all properties hav | t a response before pursuin on and the tests will then be ear programme in line with g rsued. Ing from electrical safety che ting on this. esource during peak leave p 2024, subject to access. Th e a 5-year certificate. | e were 3 properties now overdue g full Legal action. completed when the property is v good practice. The properties out ecks, the process for capturing and period. The expectation is that we e process to gain access will be f | void. standing on the 5 ye d managing these th will be close to ach | ear nrough to ieving the |
|------------------------|---|---|--|---|--|--------------------------------|
| | | Total No. properties in programme | No. compliant properties | No. Non compliant properties | Compliance % | |
| Smoke and CO alarms | Smoke detectors/alarms | 4637 | 4588 | 49 | 98.94 | |
| | CO detectors/alarms | 4261 | 4251 | 10 | 99.77 | |

| Comments | the time of the annual gas sat install detectors with remote r access. CO detectors - of the 10 prop | ety check, however de nonitoring functionality erties without detector | ue to such annual checks no y to provide assurance over rs, 2 have gas capped, with | etector installed. Detectors in prop of being undertaken at all electric the status of the devices to overc gas appliances not in use, 7 have the property, therefore none of th | properties it is prop come issues associa gas capped and no | osed to ated with no o gas |
|-------------|---|--|---|--|---|----------------------------------|
| PAT Testing | Temp furnished properties with up to date PAT tests | 21 | 21 | 0 | 100.00 | |

| Workstream | | Total No. properties in programme | No. compliant properties | No. Non compliant properties | Compliance % | Direction of travel |
|-----------------|--|---|-----------------------------|------------------------------|--------------|------------------------|
| Asbestos safety | Asbestos reinspections - non domestic areas | 358 | 358 | 0 | 100.00 | \Leftrightarrow |
| | TSM: % asbestos safety checks compliant (no properties affected) | 1872 | 1872 | 0 | 100.00 | |
| | Overdue asbestos re- inspections <3 months | 0 | | I | | |
| | Overdue asbestos re- inspections 3-6 months | 0 | | | | |
| | Overdue asbestos re- inspections 6-12 months | 0 | | | | |
| | Overdue asbestos re- inspections >12 months | 0 | | | | |
| | Asbestos re-inspections due in next 3 months | 0 | | | | |
| | | High risk | Medium risk | Low risk | Total | |
| | Overdue actions <3 months | Unknown | Unknown | Unknown | | |
| | Overdue actions 3-6 months | Unknown | Unknown | Unknown | | |
| | Overdue actions <3 months | Unknown | Unknown | Unknown | | |

| Comments | All surveys and re-inspection of non domestic areas remain in date. Any actions arising from these surveys are considered and, where appropriate, orders for remediation raised, there are no high risk occurrences within the inspected materials. 20 blocks are due for resurvey in Aug 24. |
|----------|---|
| | Procurement is currently in progress for new survey/analytical and remediation contracts. It is expected that contracts will be awarded by early October, with mobilisation of the survey/analytical contract taking approx. 2 months. Under the new contract the third party contractor will host the asbestos register together with a portal, this will provide improved access to asbestos information for CBC and contractors. In addition the contractor will provide plain English reports for residents on asbestos within their homes. |
| | Further work is required to enable reporting on the status of actions arising from asbestos surveys. |
| | Of the relevant homes, 51% currently have asbestos management surveys in place, with surveys undertaken on void properties where required and targeted R&D surveys in advance of intrusive works. Under the new contract the programme of domestic surveys will be accelerated to achieve 100% survey of relevant (pre 2000) homes by 2027. |
| | |
| | |
| | |

| Workstream | | Total No. properties in programme | No. compliant properties | No. Non compliant properties | Compliance % | Direction of travel |
|--------------|---|---|------------------------------|------------------------------|--------------|------------------------|
| Water safety | Legionella risk assessments | 25 | 25 | 0 | 100.00 | ŧ |
| | TSM: % water safety checks compliant (no properties affected) | 243 | 243 | 0 | 100.00 | † |
| | Legionella risk assessments due in the next 3 months | 0 | | | | |
| | | No. high risk remedials | No. medium risk remedials | No. low risk remedials | Total | |
| | Overdue water safety remedial actions <3 months | 0 | 2 | 0 | 2 | |
| | Overdue water safety remedial actions 3-6 months | 7 | 0 | 0 | 7 | |
| | Overdue water safety remedial actions 6-12 months | 0 | 0 | 0 | 0 | |
| | Overdue water safety remedial actions >12 months | 0 | 0 | 0 | 0 | |
| | | 7 | 2 | 0 | 9 | |

| Comments | N.B. the TSM does not include for James Donovan Court as this is 100% leasehold. A total of 2 actions were closed last month. |
|----------|---|
| | Of the 9 open actions: - 5 (4 high, 1 medium priority) relate to providing safe access to inspect water tanks as the access hatches are located over stairwells, an instruction has been issued to our consultant to review how safe access can be gained - 2 (both high) relate to descaling of outlets, these have subsequently been completed - 2 (1 high, 1 medium) relate to flushing, this has been delayed due to the guest room at the scheme being occupied |

| Workstream | | Total No. properties in programme | No. compliant properties | No. Non compliant properties | Compliance % | Direction of travel |
|-------------|--|---|------------------------------|------------------------------|---------------------------------|------------------------|
| Lift safety | Passenger lifts (LOLER) servicing | 16 | 16 | 0 | 100.00 | 1 |
| | TSM: % lift safety checks compliant (no properties affected) | 262 | 262 | 0 | 100.00 | |
| | No. stair lifts/through floor lifts with current LOLER certificate | 71 | 71 | 0 | 100.00 | |
| | LOLER inspections due in the next 3 months | 0 | | I | | |
| | | High Priority | Medium Priority | Low Priority | Total no. Overdue actions | |
| | Overdue remedial actions <3 months | 0 | 0 | 0 | 0 | |
| | Overdue remedial actions 3-6 months | 0 | 0 | 0 | 0 | |
| | Overdue remedial actions 6-12 months | 0 | 0 | 0 | 0 | |
| | Overdue remedial actions >12 months | 0 | 0 | 0 | 0 | |
| Comments | As at 31st July All LOLER in | spections are within da | te with no outstanding actio | ns | | |

| Workstream | | No. open cases | Open cases categorised as HHSRS Category 1 | Direction of travel |
|--------------|------------------------------|---------------------------------|--|---------------------------------------|
| Damp Mould & | Damp and mould cases | 177 | 0 | 1 |
| Condensation | Cases overdue <3 months | | | |
| | Cases overdue 3-6 months | | | |
| | Cases overdue 6-12 months | | | |
| | Cases overdue >12 months | | | |
| Comments | new case and resolve as per | our procedure, prioritising and | 23 in June, there are no HHSRS Cat 1 case d responding according to risk and severity to sure all front-line staff are aware of what to do | reduce health risk for our tenants as |