2013/14 Programme Maintenance - Original Budgets

Property Name	Description	
All Properties (H&S)	Consequential works from risk management inspections	
	Consequential works from Health & Safety inspections	
All Properties (WC's)	General running repairs and redecorations to Public WC's	
Ant Callery/Museums	Cyclical wiring test & consequential repairs	
Art Gallery/Museum	Modifications to flooring & entrance door/ redecorations to new 'Take-away' area Replacement of floor finishes inc. stair tread upgrade for DDA	
	Redecoration of rear stairs and ancillary areas	
	Upgrade of security alarm systems	
	Reconfiguration of ICT infrastructure/ new Comms Room & A/C provision	
	Modifications to WC facilities to improve disabled access and use	
	Replacement of office furniture/ storage (To accommodate restructure & TIC merger)	
Cemetery Chapel	Redecorations to all public areas	
Comptony Cardona	Replacement of lighting to energy efficient LEDs, all areas	
Cemetery Gardens	Grave/memorial maintenance/H&S repairs Access road widening and resurfacing	
Cemetery Offices	Modifications & alterations to reception area & waiting room	
	Upgrade of entrance door access provision (DDA)	
	Replacement of flat roof coverings inc. upstands/flashings	
Central Depot (Swindon Rd)	Upgrade to security/CCTV systems	
	Upgrade to fire alarm systems	
0	Resurface macadam/line painting to car park/s	
Central Nursery	Replacement of environmental control computer system/equipment	
	Refurbishment of auto roof-light ventilation equipment Replacement of thermal screens to Greenhouse 1, 2, 3 and 5	
	Refurbishment of greenhouse irrigation systems	
Charlton Kings Cemetery	Remove hardlandscaping paths	
Civic Amenity Centre	Health & Safety improvements to hard landscaping	
Contracting Contracting	Replacement of compactors	
	Provision of EA approved waste disposal/drainage system	
Clarence Street Library	Upgrading of fire alarm control panel link (50-50 funding)	
	Consequential repairs from fixed wire testing	
	Remedial repairs to solid floors (due to heave issues) Remedial repairs to central heating infrastructure	
	Funding from Gloucestershire County Council	
Kingham Line Bridges	Condition inspection and report	
Memorials/Statues/Fountains	Redecorations to Crimean Sebastopol War Memorial (Grant condition)	
	Remedial repairs generally (inc. lettering restoration) - St Peter's War Memorial	
Montpellier Gardens Proscenium	Redecorations to previously painted surfaces/ profiles	
Municipal Office	General repairs and redecorations	
Distrilla Orialest I Iall	Upgrades to disabled platform lift (Statutory obligations)	
Pittville Cricket Hall	Periodic cleaning of system and test	
Pittville Park Landing Stage Pittville Pump Room	Annual cleaning of decking & structure (algae removal) Update security/intruder alarm system	
r keville i dilip rkeelli	Consequential works for fixed wiring test	
	3	
	Replacement of Ballroom event lighting bars	
	Replacement of Ballroom event lighting bars Refurbish stone floor on landing	
	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system)	
	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp)	
	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test	
Pittville Rec Centre CP Pittville Recreation Centre	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp)	
	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme)	
	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme) Refurbishment of wooden sprung floors - sand/re-seal	
Pittville Recreation Centre	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme)	
Pittville Recreation Centre	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme) Refurbishment of wooden sprung floors - sand/re-seal Replacement of spa pool filter/s	
Pittville Recreation Centre	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme) Refurbishment of wooden sprung floors - sand/re-seal Replacement of spa pool filter/s Periodic cleaning of system and test Replacement of lighting lamps to main & learning pool halls General repairs and service of lighting conductor system	
Pittville Recreation Centre	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme) Refurbishment of wooden sprung floors - sand/re-seal Replacement of spa pool filter/s Periodic cleaning of system and test Replacement of lighting lamps to main & learning pool halls General repairs and service of lighting conductor system Inspection and repairs to diving board structure	
Pittville Recreation Centre	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme) Refurbishment of wooden sprung floors - sand/re-seal Replacement of spa pool filter/s Periodic cleaning of system and test Replacement of lighting lamps to main & learning pool halls General repairs and service of lighting conductor system Inspection and repairs to diving board structure General repair to spectator seating in main pool hall	
Pittville Recreation Centre	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme) Refurbishment of wooden sprung floors - sand/re-seal Replacement of spa pool filter/s Periodic cleaning of system and test Replacement of lighting lamps to main & learning pool halls General repairs and service of lighting conductor system Inspection and repairs to diving board structure General repair to spectator seating in main pool hall General repair to spectator seating in teaching pool	
Pittville Recreation Centre	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme) Refurbishment of wooden sprung floors - sand/re-seal Replacement of spa pool filter/s Periodic cleaning of system and test Replacement of lighting lamps to main & learning pool halls General repairs and service of lighting conductor system Inspection and repairs to diving board structure General repair to spectator seating in main pool hall General repair to spectator seating in teaching pool Deep clean of diving board tower, inc. repair inspection	
Pittville Recreation Centre	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme) Refurbishment of wooden sprung floors - sand/re-seal Replacement of spa pool filter/s Periodic cleaning of system and test Replacement of lighting lamps to main & learning pool halls General repairs and service of lighting conductor system Inspection and repairs to diving board structure General repair to spectator seating in main pool hall General repair to spectator seating in teaching pool Deep clean of diving board tower, inc. repair inspection Deep clean of ducting & wall tiling about diving pool/tower	
Pittville Recreation Centre Pittville Swimming Pool	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme) Refurbishment of wooden sprung floors - sand/re-seal Replacement of spa pool filter/s Periodic cleaning of system and test Replacement of lighting lamps to main & learning pool halls General repairs and service of lighting conductor system Inspection and repairs to diving board structure General repair to spectator seating in main pool hall General repair to spectator seating in teaching pool Deep clean of diving board tower, inc. repair inspection Deep clean of ducting & wall tiling about diving pool/tower Inspection and repairs of tiling to pool tank/hall walls	
Pittville Recreation Centre Pittville Swimming Pool Prince of Wales Stadium	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme) Refurbishment of wooden sprung floors - sand/re-seal Replacement of spa pool filter/s Periodic cleaning of system and test Replacement of lighting lamps to main & learning pool halls General repairs and service of lighting conductor system Inspection and repairs to diving board structure General repair to spectator seating in main pool hall General repair to spectator seating in teaching pool Deep clean of diving board tower, inc. repair inspection Deep clean of ducting & wall tiling about diving pool/tower	
Pittville Recreation Centre Pittville Swimming Pool Prince of Wales Stadium	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme) Refurbishment of wooden sprung floors - sand/re-seal Replacement of spa pool filter/s Periodic cleaning of system and test Replacement of lighting lamps to main & learning pool halls General repairs and service of lighting conductor system Inspection and repairs to diving board structure General repair to spectator seating in main pool hall General repair to spectator seating in teaching pool Deep clean of diving board tower, inc. repair inspection Deep clean of ducting & wall tiling about diving pool/tower Inspection and repairs of tiling to pool tank/hall walls Cleaning/general maintenance of running track surface	
Pittville Recreation Centre Pittville Swimming Pool Prince of Wales Stadium Promenade Long Gardens	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme) Refurbishment of wooden sprung floors - sand/re-seal Replacement of spa pool filter/s Periodic cleaning of system and test Replacement of lighting lamps to main & learning pool halls General repairs and service of lighting conductor system Inspection and repairs to diving board structure General repair to spectator seating in main pool hall General repair to spectator seating in teaching pool Deep clean of diving board tower, inc. repair inspection Deep clean of ducting & wall tiling about diving pool/tower Inspection and repairs of tiling to pool tank/hall walls Cleaning/general maintenance of running track surface Refurbishment of external paving about wall memorial (CEF 20K funded)	
Pittville Recreation Centre Pittville Swimming Pool Prince of Wales Stadium Promenade Long Gardens Sandford Park Offices	Refurbish stone floor on landing Floor maintenance scrub clean/ buff/ application coat of lacquer (Ballroom) Upgrade to passenger lift use limit (oil cooling system) Replacement of external lighting lamps (re-lamp) Periodic cleaning of system and test Replacement of lighting lamps to sports hall (re-lamp) Bird control measures to external elements (rolling programme) Refurbishment of wooden sprung floors - sand/re-seal Replacement of spa pool filter/s Periodic cleaning of system and test Replacement of lighting lamps to main & learning pool halls General repairs and service of lighting conductor system Inspection and repairs to diving board structure General repair to spectator seating in main pool hall General repair to spectator seating in teaching pool Deep clean of diving board tower, inc. repair inspection Deep clean of ducting & wall tiling about diving pool/tower Inspection and repairs of tiling to pool tank/hall walls Cleaning/general maintenance of running track surface Refurbishment of external paving about wall memorial (CEF 20K funded) Replacement of flat roof coverings (partial)	

Property Name	Description	
Town Hall	Professional fees in association with Corridor refurbishment	
	Removal of asbestos substances from floor voids - Phase 1	
	Overhaul repairs and redecoration of corridor/ room doors (Grd)	
	Overhaul repairs and redecoration of corridor/ room doors (1st)	
	Consequential repairs required by wiring cyclical test	
	Rewiring programme of replacement	
	Lighting programme of replacement to corridors (fittings)	
	Replacement of Kitchen cooker/oven equipment	
	Provision of a portable wheelchair lift	
	Installation of wireless hearing loop to Drawing Room	
	Refurbishment of fixed seating	
	Replacement of floor finishes/carpets	
	Replacement of floor finishes/carpets to main staircase	
	Refurbishment of wooden flooring - deep clean & re-wax (Tretex)	
	Remedial repairs to Telesales office floor (inc. new linings)	
	Floor maintenance scrub clean/ buff/ application coat of lacquer (main hall & stage)	
	Redecoration of walls/ceiling linings (balcony & corridors)	
	Installation of fire-rated suspended ceiling lining to Catering cellar area	
	Redecoration of walls/ceiling linings/mouldings (Grd Corridors)	
	Replacement of corridor convector heaters	
	Replacement of lagging to heating pipework	
	Refurbishment of steps to basement (to boiler room & kitchen)	
	Upgrade of stage lift barrier and interlock system	
	Emergency remedial repairs to stonework	
	Overhaul repairs and redecoration	
	Replacement of curtains/furnishings	
	Replacement of gallery window curtains	
Whaddon Road Pavilion	Replacement of HWS emersion heaters	
Christmas Illuminations	Replacement LED lighting festoons and lamp-post sails	
All Properties (Car Parks)	Periodic cleaning of underground drainage	
Honeybourne Line Millbrook St.	Install fencing	
Honeybourne Line (All Bridges)	Replace/ repair anti-bird netting	
Total Programme Maintenance agr		
	,	
2012/13 agreed works to be comple	eted in 2013/14	
Civic Amenity Centre	Renew drainage provision to spotting compound	
Recreation Centre	LED pool lights	
Total Carry Forwards from 2012/13		

Total Programme Maintenance for 2013/14

Tot	tal £
	5,000
	5,000
	5,000
	2,500
	8,000
	10,000
	8,000
	20,000
	12,000
	20,000
	13,000
	10,000
	7,000
	6,000
	20,000
	15,000
	-,
	15,000
	20,000
	20,000
	18,000
	30,000
	25,000
	15,000
	16,000
	5,000
	20,000
	20,000
	50,000
	2,000
	3,000
	25,000
	5,000
	-17,500
	2,000
	5,000
	6,000
	8,000
	10,000
	3,500
	500
	250
	20,000
	5,000
	5,000
	10,000
	2,500
	6,000
	1,000
	1,000
	3,000
	2,000
	10,000
	7,000
i	
	1,000
	1,000 2,000
	1,000 2,000 5,000
	1,000 2,000 5,000 1,000
	1,000 2,000 5,000 1,000 4,000
	1,000 2,000 5,000 1,000 4,000 4,000
	1,000 2,000 5,000 1,000 4,000 4,000 1,000
	1,000 2,000 5,000 1,000 4,000 4,000 1,000
	1,000 2,000 5,000 1,000 4,000 4,000 1,000 2,000
	1,000 2,000 5,000 1,000 4,000 4,000 1,000 2,000 7,000
	1,000 2,000 5,000 1,000 4,000 4,000 1,000 2,000 7,000 2,000
	1,000 2,000 5,000 1,000 4,000 1,000 2,000 7,000 2,000 15,000
	1,000 2,000 5,000 1,000 4,000 1,000 2,000 7,000 2,000 15,000 8,000
	1,000 2,000 5,000 1,000 4,000 1,000 2,000 7,000 2,000 15,000 8,000 40,000
	1,000 2,000 5,000 1,000 4,000 1,000 2,000 7,000 2,000 15,000 8,000

5,000 10,000 22,000 4,000 1,000 5,000 10,000 12,000 8,000 15,000 41,000 5,000 2,500 8,000 10,000 3,000 2,000 8,000 10,000 5,000 10,000 6,000 5,000 10,000 6,000 10,000 3,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000	
10,000 22,000 4,000 1,000 5,000 10,000 12,000 8,000 15,000 41,000 5,000 3,000 2,500 8,000 10,000 30,000 2,000 10,000 6,000 5,000 10,000 6,000 10,000 30,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 5,000 10,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000	Total £
10,000 22,000 4,000 1,000 5,000 10,000 12,000 8,000 15,000 41,000 5,000 3,000 2,500 8,000 10,000 30,000 2,000 10,000 6,000 5,000 10,000 6,000 10,000 30,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 5,000 10,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000	5,000
22,000 4,000 1,000 5,000 10,000 12,000 8,000 15,000 41,000 5,000 3,000 2,500 8,000 10,000 30,000 2,000 10,000 6,000 5,000 10,000 6,000 10,000 30,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 5,000 10,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000	
4,000 1,000 1,000 10,000 12,000 8,000 15,000 41,000 5,000 3,000 2,500 8,000 10,000 30,000 2,000 10,000 6,000 5,000 10,000 10,000 6,000 10,000 30,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 5,000 10,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000	22,000
5,000 10,000 12,000 8,000 3,000 15,000 41,000 5,000 2,500 8,000 10,000 30,000 2,000 6,000 10,000 6,000 10,000 600 10,000 30,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 5,000 10,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000	
10,000 12,000 8,000 3,000 15,000 41,000 5,000 2,500 8,000 10,000 2,000 6,000 10,000 10,000 10,000 10,000 10,000 3,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 5,000 10,000 5,000 5,000 5,000 5,000 5,000	1,000
12,000 8,000 3,000 15,000 41,000 5,000 2,500 8,000 10,000 30,000 5,000 10,000 6,000 10,000 600 10,000 30,000 5,000 10,000 5,000 5,000 10,000 5,000 5,000 10,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000	5,000
8,000 3,000 15,000 41,000 5,000 3,000 2,500 8,000 10,000 30,000 5,000 10,000 6,000 10,000 600 10,000 3,000 3,500 5,000	10,000
3,000 15,000 41,000 5,000 3,000 5,000 2,500 8,000 10,000 30,000 2,000 10,000 6,000 10,000 10,000 10,000 30,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 5,000 10,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000	12,000
3,000 15,000 41,000 5,000 3,000 5,000 2,500 8,000 10,000 30,000 2,000 10,000 6,000 10,000 10,000 10,000 30,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 10,000 5,000 5,000 10,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000 5,000	8,000
41,000 5,000 3,000 5,000 2,500 8,000 10,000 30,000 2,000 8,000 5,000 10,000 6,000 5,000 10,000 600 10,000 3,000 5,000 5,000 10,000 5,00	
41,000 5,000 3,000 5,000 2,500 8,000 10,000 30,000 2,000 8,000 5,000 10,000 6,000 5,000 10,000 600 10,000 3,000 5,000 5,000 10,000 5,00	15,000
3,000 5,000 2,500 8,000 10,000 30,000 2,000 8,000 5,000 10,000 6,000 10,000 600 10,000 3,000 3,500 5,000	41,000
5,000 2,500 8,000 8,000 10,000 30,000 2,000 8,000 5,000 10,000 6,000 10,000 600 10,000 3,000 3,500 5,000	5,000
2,500 8,000 10,000 30,000 2,000 8,000 5,000 10,000 6,000 10,000 600 10,000 3,000 3,500 5,000	3,000
8,000 8,000 10,000 30,000 2,000 8,000 5,000 10,000 6,000 10,000 600 10,000 3,000 3,500 5,000	5,000
8,000 10,000 30,000 2,000 8,000 5,000 10,000 6,000 5,000 10,000 600 10,000 3,500 5,000	2,500
10,000 30,000 2,000 8,000 5,000 10,000 6,000 10,000 600 10,000 3,000 3,500 5,000	8,000
30,000 2,000 8,000 5,000 10,000 6,000 5,000 10,000 600 10,000 3,000 3,500 5,000	8,000
2,000 8,000 5,000 10,000 6,000 5,000 10,000 600 10,000 3,000 3,500 5,000	10,000
8,000 5,000 10,000 6,000 5,000 10,000 600 10,000 3,000 3,500 5,000	30,000
5,000 10,000 6,000 5,000 10,000 600 10,000 3,000 3,500 5,000	2,000
10,000 6,000 5,000 10,000 600 10,000 3,000 3,500 5,000	8,000
6,000 5,000 10,000 600 10,000 3,000 3,500 5,000	5,000
5,000 10,000 600 10,000 3,000 3,500 5,000	
10,000 600 10,000 3,000 3,500 5,000	
600 10,000 3,000 3,500 5,000	5,000
10,000 3,000 3,500 5,000	10,000
3,000 3,500 5,000	600
3,500 5,000	10,000
5,000	
	3,500
992,550	992,550

20,000
10,000
30.000

1,022,550