| Property Name  | Description  | 2018/19         |
|--|--|-----------------|
|  |  | £               |
| All Properties (H&S)                                     | Consequential works arising from Fire risk assessment reports                | 20,000          |
| (100)  | Consequential works arising from legionella risk                             |                 |
| All Properties (H&S)                                     | assessments/ inspections   | 12,000          |
| All Properties (H&S)                                     | Consequential works arising from asbestos risk assessments/ inspections      | 10,000          |
| All Properties (H&S)                                     | Installation of safety filming to doors and windows                          | 3,000           |
| All Properties (H&S)                                     | Fixed Wiring inspections/ EIC Certification programme                        | 15,000          |
| All Properties (H&S)                                     | Contingency fund for compliance/ H&S remedial work                           | 10,000          |
| All Properties (H&S)                                     | Consequential works arising from Statutory Inspections                       | 15,000          |
| All Properties (H&S)                                     | Repairs to car parks pot hole and other misc repairs                         | 10,000          |
| All Properties (Energy)                                  | Energy reduction schemes LED, controls, insulation ect                       | 10,000          |
| Town Hall  | Renew intruder alarm heads   | 1,500           |
| Town Hall  | Roof repairs   | 20,000          |
| Town Hall  | Remedial repairs to CCTV system  | 2,000           |
| Town Hall  | Remedial repairs to cellar basement to prevent leaking                       | 3,500           |
| Pump Room  | Redecorations to external elevations at high level                           | 35,000          |
| Pump Room  | Remodel RWG outlet to Loggia where water staining and make good decorations  | 8,000           |
| Pump Room  | Remedial repairs to ornate internal plasterwork to ceiling                   | 5,000           |
| Pump Room  | Rebuild retaining wall outside of kitchen                                    | 3,500           |
| Pump Room  | Investigate deflection to first floor east room                              | 1,800           |
| Pump Room  | Redecorations to reception area and floor covering renewal                   | 5,000           |
|  | Replace CCTV camera to rear car park to capture whole                        | 0,000           |
| Pump Room  | area   | 1,200           |
| Pump Room  | Redecorations to external high-level windows inc., minor repairs             | 25,000          |
| Municipal Offices  | Overhaul windows - will require access equipment                             | 25,000          |
| Municipal Offices  | FRA upgrade to doors   | 16,000          |
| Municipal Offices  | Renew reception lobby flooring   | 15,000          |
| Municipal Offices  | Renew defective main roof skylights (by lift motor room)                     | 4,000           |
| Municipal Offices  | Provision of additional security to the basement area and fire escape stairs | 3,000           |
| Art Gallery & Museum                                     | Improvements to fire compartmentation form FRA report                        | 35.000          |
| Arle Nursery   | Install safety filming to glazing (legislation)                              | 10,300          |
| Arle Nursery   | Ongoing phased replacement of irrigation pipework.                           | 6,000           |
| Arle Nursery   | Reinstate automatic watering facility to Tunnels 2, 3 & 4.                   | 3,000           |
| Arle Nursery   | Repairs / refurbishment of Polythene covering / timber frame                 | 2,500           |
| Alle Nuisery   | Gym / Dance studio AHU (£60k inadequate to complete                          | 2,300           |
| Pittville Recreation Centre                              | works)   | 10,000          |
| Pittville Recreation Centre                              | Replace damaged fencing to CHP external radiator                             | 4,000           |
| Pittville Recreation Centre                              | Tree works to Hudson Street ( combined with Green Space contribution)        | 22,000          |
|  | Cathodic protection to Basement area (ongoing structural                     | ·               |
| Pittville Recreation Centre                              | repair works)  | 20,000          |
| Pittville Recreation Centre  Pittville Recreation Centre | Repairs to Wet changing areas floor tiling  General redecorations            | 12,000<br>5,000 |
| Pittville Recreation Centre  Pittville Recreation Centre | Repairs to poolside tiling   | 10,000          |
| Pittville Recreation Centre                              | Main hall - Seat replacements (ongoing)                                      | 9,000           |
| Cemetery & Crematorium                                   | Road resurfacing programme   | 20,000          |
| Cemetery & Crematorium                                   | Repairs and decoration to grade II Arbour houses                             | 15,000          |
| QE11 Playing Field                                       | Annual leachate removal from catch-pit                                       | 1,500           |
| Honneybourne railway bridges                             | Remedial repairs to bird netting   | 6,000           |
| Pilley footbridge  | Remedial structural repairs and re-painting                                  | 110,000         |
| Burrows Pavillion  | Replacement of non-slip floor coverings in shower area/s                     | 3,500           |
| Cenotaph War memorial                                    | DOF Stone cleaning   | 4,200           |
| St Marys Mission   | Repainting and remedial repairs to rendering                                 | 3,500           |
|  | Tropainting and remedial repairs to remaching                                |                 |
| Long Gardens   | Restoration of stone base to lamp standards                                  | 8,000           |